

MC 500 AND 600 PARTS LIST (REFER TO DIAGRAM) SPECIFY MODEL WHEN ORDERING PA

- 1 Cast Control Knob
- 2 Cast Control Washer
- 3 O-Ring
- 4 Brass Ball Bearing
- 5 Screw
- 6 Left Side Plate
- 7 Bait Clicker Button
- 8 Bait Clicker Button Washer
- 9 Pawl
- 10 Pawl Spring
- 11 Latch Spring
- 12 Location Pillar
- 13 Pawl Washer
- 14 E-Ring
- 15 Level Wind Gear
- 16 Magnetic Knob
- 17 Magnetic Knob Washer
- 18 Magnet plate
- 19 Magnetic Pawl
- 20 Magnetic Pawl Pillar
- 21 Magnetic Pawl Spring
- 22 Magnet Anti-Rotate Plate
- 23 Magnet Trough
- 24 Worm Shaft
- 25 Line Guard
- 26 Line Guide
- 27 Bushing
- 28 Washer
- 29 Line Guide Pawl
- 30 Washer
- 31 Line Guide Pawl Cap
- 32 Main Body Assembly
- 33 Clutch Bar
- 34 Spool
- 35 Anti-Rotate Plate
- 36 Friction Brake Shoe
- 37 Spool Shaft
- 38 Right Gear Plate
- 39 Crankshaft
- 40 Clutch Disc
- 41 Big Washer
- 42 Drag Friction Disc
- 43 Main Gear
- 44 Bowl Washer
- 45 Anti-Reverse Ball Bearing Cone
- 46 Drag Spring Washer

- 47 Clutch Plate
- 48 Clutch Pawl
- 49 Clutch Pawl Spring
- 50 Clutch stick
- 51 Yoke
- 52 Pinion Gear
- 53 Right Side Plate
- 54 Ball Bearing
- 55 Cast Control Knob
- 56 Star Drag Handle
- 57 Handle Spring Washer
- 58 Handle
- 59 Washer
- 60 Handle Nut
- 61 Latch Keeper

RTS